



**Drobo B810n Firmware  
Release Notes  
Release Date: Dec 11, 2015**

**CONTENTS**

---

VERSION INFORMATION  
KEY HIGHLIGHTS  
KNOWN ISSUES  
RELATED TECHNICAL DOCUMENTATION

**VERSION INFORMATION**

---

Drobo Firmware: Version 3.5.3 [9.30.78445]

**KEY HIGHLIGHTS**

---

This is a firmware update for B810n.

- Fix an issue with the power LED

**KNOWN ISSUES**

---

General Issues

**None**

**BEST PRACTICES**

---

In accordance with industry best practices, you should always backup your data before any firmware upgrade. For more information, please visit [www.drobo.com/support](http://www.drobo.com/support).

Make sure that you keep all software up to date. This includes Drobo Dashboard, which as of this writing the latest release is 2.7.1.

**RELATED TECHNICAL DOCUMENTATION**

---

Current Drobo technical reference materials are available on the Drobo Support Website (<http://www.drobo.com/support.html>). This includes:

- *Knowledge Base*
- *Best Practices*
- *Product Documentation*
- *Drobo Help for Mac*
- *Drobo Help for PC*

Copyright 2015 Drobo, Inc. Data Robotics, Drobo, and BeyondRAID are trademarks of Drobo, Inc., which may be registered in some jurisdictions. All other trademarks used are owned by their respective owners. All rights reserved. Specifications subject to change without notice.

P/N 081-00042-001 Rev 01